

Coal also contains inorganic components, known as *ash*. Ash includes mi
pyrite and marcasite formed from metals that accumulated in the living t
ancient plants. Quartz, clay, and other minerals are also added to coal d
and groundwater. Ash lowers the fixed carbon content of coal, decreasing

1 | 2 | 3 | 4 | 5 | 6 | 7

Next >



Find in this article



View printer-friendly page



Edit this article

Rate this

low



How to cite this article

© 1993-2005 Microsoft Corporation. All Rights Reserved.

Suggest Updates

Want to help us improve this article? You can edit this article or you can suggest updates or
corrections in the box below.

|

Send

© 2005 Microsoft MSN Privacy Legal Advertise

Feedback Help

Ex 15